

Technical Bulletin

April 2023 - TSB-VSA-VLS-042023-01

TIPS AND TRICKS

Headlamp

All models

Condensation phenomena



There are two types of condensation:

1. Normal condensation:

The moisture occurred inside the headlamp during the raining or car washing. The water is in **vapor state** and replacement is not required (see Fig. 1)



2. Abnormal condensation (water leak):

The water is locating in the bottom of the headlamp and cannot be removed by heating of the lamp.

The causes are **cracks** or **improper fitment** and the replacement is required see (Fig. 2)



Website valeoservice.com



Technical Assistance0 810 600 606


Smart care for you valeoservice.com





Technical Bulletin

Procedure of removing the vapor



1. Remove the **dust cover(s)** from behind of headlamp as shown in Fig. 3.

 Check the headlamp ventilation and make sure there is **no blockage** as shown in Fig. 4.

3. Turn on the engine then switch on the **high beam lights** as shown in Fig. 5.

4. Keep the engine run on idle speed for **30 mins**.



Website valeoservice.com



Technical Assistance 0 810 600 606

Smart care for you valeoservice.com