



News

**Brake wear indicator hole removal
OptiPACK / SmartPACK**


Concerned references

OptiPACK	882200, 882223, 882229, 882230, 882238, 882291, 882423, 882222, 882233, 882234, 882235, 882227, 882228, 882251, 882250, 882289, 882208, 882204, 882205, 882206, 882201, 882203
SmartPACK	882400, 882404, 882408, 882428, 882450

The hole removal reasons

- All sensors in OptiPACK / SmartPACK box are not fit on the hole but on the sensor's socket at the backplate.
- New vehicles are not equipped with brake pad wear sensor.
- All major premium competitors already removed the holes.

Q&A

Question	Answer
Where is the removed hole?	
Is there an impact on the product weight?	The impact is 12g / 0,01% on a complete set. It does not affect the product weight.
What does it change for Divisions?	It does not change anything Grantex logistic will inform each Division at the 1st shipment of the modified pads.



Website
valeoservice.us/en-us



Technical Assistance
1-888-718-2536

valeoservice.us

